

# 228 Bernhard Rd



Pre-construction Photo



Construction Photo



Post Construction Photo



<b>Date Updated:</b>	7/12/2016
<b>Cost Estimate:</b>	\$5,520.98
<b>Est. Project Length:</b>	1 Week
<b>Construction:</b>	Complete
<b>Property Access:</b>	
<b>Utilities:</b>	
<b>Preliminary Eng:</b>	
<b>Right Of Way:</b>	
<b>Construction:</b>	Complete
<b>Contractor:</b>	McCoy Grading
<b>Const Start Date:</b>	3/7/2016
<b>Completion Date:</b>	3/14/2016
<b>Problem:</b>	Washout around an undersized 36 in. diameter corrugated metal pipe inlet caused shoulder and pipe failure.
<b>Proposed Solution:</b>	Replace the current pipe with a 42 in. reinforced concrete pipe and headwalls.
<b>Percent Complete:</b>	100
<b>Current Status:</b>	Complete
<b>Total Cost:</b>	\$46,257



**Photo 1: Completed project. Photo captures new headwall that was installed.**



**Photo 2: Completed project. New headwalls and rock are visible on both sides of the road.**



**Photo 1: Installation of 42" concrete pipe. (03/07/2016)**



**Photo 2: Installation of headwall and location grading. (03/08/2016)**



Project: 228 Bernhard Road – 2017 SPLOST

Date: March 2016



**Photo 1: Pre-existing conditions.**



**Photo 2: Pre-existing conditions.**



Project: 228 Bernhard Road – 2017 SPLOST

Date: December 2015