



Photo 1: Pipe condition prior to replacement. (01/04/2018)



Photo 2: New pipe has been installed and soil stabilization placed along project location. The project was completed on 02/20/2018. (02/28/2018)



Project: 133 Laura Lane – 2017 SPLOST

Date: 01/04/2018 & 02/28/2018